

CJCF PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)		
HIDEO NANATAKI ET AL.	:	Examiner: Sandra L.	Brase
IIIDEO NANATAKI ET AL.	: Group Art Unit: 2852		
Appl. No.: 10/717,478)	•	
Filed: November 21, 2003	:		Certificate
·	:		MAY 0 3 2006
For: IMAGE HEATING APPARATUS)		
HAVING MULTIPLE ROTATABLE	:		of Correction
MEMBERS AND TEMPERATURE)		
DETECTING ELEMENT	:		
)		
U.S. Patent No.: 6,985,689 B2	:		
)		
Issued: January 10, 2006	:	April 28, 2006	
Commissioner for Patents			
P.O. Box 1450		05/01/2006 JADDO1	20000400 400040
Alexandria, VA 22313-1450			00000102 6985689
		01 FC:1811	199 99 0

CERTIFICATE OF CORRECTION UNDER RULE S 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

MAY 4 ZUUG

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Lawrence Á. Štahl Attorney for Patentees Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,985,689 B2

DATED

January 102006

INVENTOR(S) :

HIDEO NANATAKI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET NO. 3 of 9:

Figure 3, "ECOND" should read -- SECOND--.

COLUMN 4:

Line 4, "an" (both occurrences) should read --a--.

Line 6, "an" should read --a--.

COLUMN 7:

Line 18, "adjust" should read --adjusts--.

COLUMN 8:

Line 2, "have" should read --has--.

Line 7, "avoids" should read --avoid--.

Line 64, "direct" should read --in direct--.

COLUMN 10:


Line 57, "form" should read --from--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. 6,985,689 B2

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82)

(Form#30)

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,985,689 B2

DATED

January 102006

INVENTOR(S) :

HIDEO NANATAKI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 15, "elements" should read --element--. Line 18, "contacts" should read --contact--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

No. of add'l. copies @ 30¢ per page



PATENT NO. 6,985,689 B2

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,985,689 B2

DATED

January 102006

INVENTOR(S) :

HIDEO NANATAKI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET NO. 3 of 9:

Figure 3, "ECOND" should read -- SECOND--.

COLUMN 4:

Line 4, "an" (both occurrences) should read --a--.

Line 6, "an" should read --a--.

COLUMN 7:

Line 18, "adjust" should read --adjusts--.

COLUMN 8:

Line 2, "have" should read --has--.

Line 7, "avoids" should read --avoid--.

Line 64, "direct" should read --in direct--.

COLUMN 10:

Line 57, "form" should read --from--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

MARS A 2006.

PATENT NO. 6,985,689 B2

No. of add'l. copies @ 30¢ per page

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,985,689 B2

DATED

January 102006

INVENTOR(S) :

HIDEO NANATAKI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 15, "elements" should read --element--. Line 18, "contacts" should read --contact--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. 6,985,689 B2

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) (Form#30)